



Bulmetal

Bulonería Industrial

▣ TABLA DEL SISTEMA WHITWORTH

Diámetro exterior en pulgadas	Número de hilos por pulgada	DIMENSIONES EN MILÍMETROS			
		Diámetro exterior	Diámetro medio	Diámetro del núcleo	Paso
1/8	40	3,175	2,768	2,362	0,635
5/32	32	3,969	3,461	2,952	0,794
3/16	24	4,762	4,085	3,407	1,058
7/32	24	5,556	4,879	4,201	1,058
1/4	20	6,349	5,536	4,723	1,269
5/16	18	7,937	7,033	6,130	1,411
3/8	16	9,524	8,508	7,492	1,587
7/16	14	11,120	9,950	8,789	1,814
1/2	12	12,699	11,344	9,989	2,116
9/16	12	14,287	12,931	11,576	2,116
5/8	11	15,874	14,396	12,918	2,309
11/16	11	17,465	15,983	14,505	2,309
3/4	10	19,049	17,423	15,797	2,539
13/16	10	20,637	19,010	17,384	2,539
7/8	9	22,224	20,417	18,610	2,822
15/16	9	23,812	22,004	20,197	2,822
1	8	25,399	23,366	21,333	3,174
1 1/8	7	28,574	26,251	23,927	3,628
1 1/4	7	31,749	29,426	27,102	3,628
1 3/8	6	34,924	32,213	29,502	4,233
1 1/2	6	38,099	35,388	32,677	4,233
1 5/8	5	41,279	38,021	34,768	5,079
1 3/4	5	44,449	41,196	37,943	5,079
1 7/8	4,5	47,624	44,099	40,395	5,644
2	4,5	50,799	47,184	43,570	5,644